# **EXCAVATOR QUICK GUIDE**

### Excavator Responsibilities - Know the Basics!


#### Plan for Your Excavation

You are required to use white markings to define the entire area where excavation will occur, unless it can be shown it is not practical. Include a safety buffer when marking the area.

#### Notify GSOC

All Minnesota excavators, including homeowners and farmers, are responsible for notifying GSOC of their proposed excavations so facility operators with underground facilities near the excavation site can be informed of pending excavation. Excavators are required to notify GSOC 48 hours in advance, excluding weekends and holidays, before beginning excavation.

## The color of paint or flags identifies the type of underground facility



# EXCAVATOR QUICK GUIDE

#### File Locate Requests by Phone

Emergency	866-640-3637
Twin Cities Metro	651-454-0002
Greater MN Area	800-252-1166
Nationally	

#### File Locate Requests Online

www.gsocsubmit.org

#### Search for Tickets Online

www.gsocsearch.org

#### Visit our Website

www.gopherstateonecall.org

#### **Contact Customer Support**

By phone: 651-681-7326

By email: customersupport@gopherstateonecall.org

#### **Private Facilities**

Some underground lines in your work area may not be utility owned. These are considered private facilities and will NOT be marked by public utility companies. Inspect your job site prior to entering a ticket for clues as to where private facilities may be buried. Investigate who may have installed them and determine if any records or maps exist. Suggest that the property owner hire a private utility locator. A list of private locators can be found at -

> Ainnesota Regional

http://gopherstateonecall.org/private-facility-locators

### www.gopherstateonecall.org